

Safety Performance

LTIFR	unit	2014	2015	2016	2017
Employees	Case/Million hours	0	0	0	0
Contractors	Case/Million hours	*	0	0.3	0

* 2014 LTIFR was 2.69 which calculated by combining employees and contractors.

In 2014, there was a case for accident causing the contractor death. After this accident, EGCO had determined the cause of death suddenly and provide the assistance and compensation to the death's family. Nevertheless, EGCO Group's power plants has reviewed and improved their safety standards more securely as well as strictly controlled its operations in order not to repeat the same mistake which may bring about the loss of lives and property unacceptable by EGCO Group.

In 2016, O&M Contractor step on upper case to check rice hulk flow and the right foot went through rusty upper casing plate causing 3 days LTA for ankle injury. For corrective and preventive action, there was a Prohibit sign not to step on the upper case, replace all rusty casing plate, revised the procedure of fuel flow checking and move the hand hole to outside for convenience to access without step over the upper case.